




FARGO® HDP®5600 PRINTER FIRMWARE

RELEASE NOTES

Firmware Version: 6.8.4

PLT-04725, Rev. A.0

September 2019



Copyright

© 2019 HID Global Corporation/ASSA ABLOY AB. All rights reserved.

This document may not be reproduced, disseminated or republished in any form without the prior written permission of HID Global Corporation.

Trademarks

HID GLOBAL, HID, the HID Brick logo, the Chain Design, HDP, and FARGO are trademarks or registered trademarks of HID Global, ASSA ABLOY AB, or its affiliate(s) in the US and other countries and may not be used without permission. All other trademarks, service marks, and product or service names are trademarks or registered trademarks of their respective owners.

Revision history

Date	Description	Revision
September 2019	Release Notes for Firmware version 6.8.4.	A.0

Contacts

For additional offices around the world, see www.hidglobal.com/contact/corporate-offices.

Americas and Corporate	Asia Pacific
611 Center Ridge Drive Austin, TX 78753 USA Phone: +1 866 607 7339 Fax: +1 949 732 2120	19/F 625 King's Road North Point, Island East Hong Kong Phone: +852 3160 9833 Fax: +852 3160 4809
Europe, Middle East and Africa (EMEA)	Brazil
Haverhill Business Park, Phoenix Road Haverhill, Suffolk, CB9 7AE United Kingdom Phone: +44 (0) 1440 711 822 Fax: +44 (0) 1440 714 840	Condomínio Business Center Av. Ermano Marchetti, 1435 Galpão A2 - CEP 05038-001 Lapa - São Paulo / SP Brazil Phone: +55 11 5514-7100

HID Global Technical Support: www.hidglobal.com/support.

1 Scope

These release notes provide information on the FARGO® HDP®5600 Printer Firmware version 6.8.4. Included are product enhancements, fixes, known issues, and limitations since the previous release.

Note: The reference numbers associated with these features, issues, and fixes are from HID Global tracking systems.

2 New features

Added the **Apply Additional Film Transfer Layer** option to the **Image Transfer** tab of the **Printer Preferences**.

Note: This option requires firmware version 6.8.4 (FRW-00758 Rev. G) or higher and Windows driver software version 1.2.0.5 (SFW-01106 Rev. E) or higher.

3 Resolved issues

- Reduced roller wear of the Financial Magnetic Encoding Module, which can cause card jam errors (Reference No. ISU-9320).
- Improved ribbon handling for YMCKIKI, YMCKI, and YMCKH ribbons, which could cause excessive ribbon usage (Reference No. ISU-7196).
- Improved image transfer quality for the first few cards printed after a pause (Reference No. ISU-7792).

